

Attn: Corey Geiger, COO, IronRidge Inc.

Date: June 24th, 2022

Re: Structural Certification for IronRidge All Tile Hook with Aire Dock (P/N: AE-ATH-01-M1)

This letter addresses the structural capacity of IronRidge All Tile Hook with Aire Dock for use as a tile roof attachment for the IronRidge Aire system. The assembly consists of a cold formed stainless steel arm & base, an extruded aluminum dock (Aire Dock), and an optional aluminum flashing. The All Tile Hook base is attached to an underlying roof rafter using two (2) 5/16" stainless steel lag bolts and the arm is secured to the base by a 5/16" carriage bolt. Aire Dock is assembled onto the vertical slot of the arm with a 3/8" stainless steel bolt. All Tile Hook with Aire Dock shall be installed in accordance with IronRidge's Aire All Tile Hook installation manual. Full assembly details are shown in Exhibit EX-0022.

The referenced uplift, compression, and lateral capacities tabulated below are based on mechanical load tests performed on All Tile Hook as a stand-alone attachment excluding the Aire Dock (reference Table 1 note 6). Load tests were conducted along the four load directions shown in Figure 1, using a Universal Instron Test Unit, conforming to the following standards:

ASTM D1761-20, Standard Test Methods for Mechanical Fasteners in Wood and Wood Based Materials ASTM A370-21, Standard Test Methods and Definitions for Mechanical Testing of Steel Products NDS-2015, National Design Specification (NDS) for Wood Construction ICC-AC428, Acceptance Criteria for Modular Framing Systems Used to Support Photovoltaic (PV) Modules

The uplift, compression, and lateral load testing was performed by installing the All Tile Hook assembly on a sample roof deck composed of 15/32" OSB board over 24" O.C. 2x4 Douglas Fir rafters. The measured rafter average specific gravity and moisture contents are 0.37 and less than 16%, respectively. For each test the arm component was set at the furthest allowable position from the lag bolts and loads were directly applied at the highest slot position along the center line of the arm as shown in Figure 1 in order to perform the tests at the worst configuration.

The ultimate failure mode for uplift testing was pull out of the lag bolts from the rafters and for compression testing the ultimate failure mode was rupture of the OSB board due to compression bearing of the arm. The averages of the peak loads of both directions, which were observed concurrent with the respective ultimate failure point, are documented in Table 1 below.

The ultimate failure mode for both lateral directions was pull out of the lag bolts from the rafters. Average peak loads of 2315 lbs. and 619 lbs. were recorded for the direction parallel to rafter and direction perpendicular to rafter respectively. The associated lateral movements at the loading point were observed to be 7" and 10" respectively. To restrict system deformation under lateral loads, a deflection based serviceability limit was applied, which consequently results in a reduced allowable capacity. The serviceability limit determined loads are reported as the allowable capacity for both lateral load directions as tabulated in Table 1. Specifically, based on full scale lateral testing, a 1" lateral arm deflection is confirmed compatible with the full-scale system and presented as the serviceability limit for the load direction parallel to rafter. For the lateral load direction perpendicular to rafter, the Instron recorded proportional limit of 0.75" is presented as the serviceability limit which eliminates permanent deformation of the assembly.



Observed test results and failure modes along with allowable capacities are summarized in the Table 1.

Table 1: IronRidge All Tile Hook with Aire Dock Mechanical Load Test Results & Allowable Capacities (1)(6)							
Load Direction	Specimen Quantity	Observed Failure Mode	Average Peak Load at Failure (lbs) <sup>(2)</sup>	Safety Factor <sup>(3)</sup>	Deviation of Test Results <sup>(4)</sup>	Allowable Load (lbs)	
Uplift	4	Lag Bolt Pull-out	1011	3.0	10.6%	337	
Compression	4	OSB Deck Rupture	709	2.54	10.3%	279	
Lateral Parallel to Rafter	4	Lag Bolt Pull-out	2315	3.0	5.4%	154 <sup>(5)</sup>	
Lateral Perpendicular to Rafter	4	Lag Bolt Pull-out	619	3.0	8.0%	75 <sup>(5)</sup>	

- (1.) Capacities apply to rafter size of 2x4 or greater at 24" O.C. or less, deck thickness 15/32" or greater, and rafters with a Specific Gravity of 0.37 or greater. The specific gravity during testing was measured and recorded per ASTM D2395-17 "Standard Test Methods for Density and Specific Gravity of Wood and Wood-based Materials."
- (2.) Values are based on securing lag bolt within center 1/3 of rafter width with a minimum 2.5" end distance.
- (3.) Safety factor is associated with respective failure modes per ASTM D7147-21 and NDS-2015.
- (4.) Deviation refers to the highest or lowest test value to the group average and is based on the ultimate peak load for the tension/compression and serviceability limit load for the lateral directions.
- (5.) The provided allowable loads are controlled by the specified serviceability limit.
- (6.) The allowable capacities are based on the load tests for All Tile Hook as a stand-alone attachment with no Aire Dock. Additional load tests were performed on All Tile Hook and Aire Dock as an assembly and confirm that the failure mode observed in each load direction was consistent with the previous stand-alone attachment tests, therefore the allowable capacities in Table 1 are applicable as well to All Tile Hook with Aire Dock.





Figure 1

Sincerely,



Gang Xuan, SE Senior Structural Engineer



ITEM NO.	DESCRIPTION			
1	assy, flashing			
2	BOLT, LAG 5/16 X 4"			
3	ASSY, BASE			
4	BOLT, CARRIAGE 5/16 x 1"			
5	ASSY, ALL TILE HOOK			
6	ASSY, AIRE DOCK			

